

**Limitless Devices – Gen 4 Levo (Specialized 3.1)**

The removal or adjustment to ebike speed limit in public areas such as streets and cycle paths is illegal.

By fitting this device, the owner of the pedal assisted bicycle accepts full liability and responsibility for any incidents and consequential damages including and not limited to personal injury, death, injury to other persons or animals and property.

The manufacturer declines all responsibility for any damage or loss caused by pedal assisted bicycles fitted with this system.

The manufacturer declines all responsibility for any personal injury, death, injury to other persons or animals including damage to any property.

Remove the two bolts retaining the lower Motor Cover:



Remove the cover, noting the speed sensor cable placement at rear of motor (recess for cable)




Unplug the Speed Sensor Cable from the motor and install the cable clamp provided as pictured:



Plug the Limitless Device into Motor with marking facing upwards. (Please note orientation of flat tab within connector)

Loop cable under main power harness as pictured.




Plug Limitless Cable into the bikes Speed sensor connector (please note marking for orientation)

Use supplied zip tie to clamp cable (once connected)



Zip tie cable to main power harness as shown below, making sure that once completed that nothing will foul the bash guard when re-assembling. Cut excess off of zip tie.



Re-attach Bashguard ensuring that the speed sensor cable is within recess behind motor and that the fitted limitless device cable is not pinched by the bashguard when seated.



Thank you for your custom and enjoy your ride.



